

Fire Risk Assessment



Carried out on behalf of

1-70 Perryman House - Barking - 900011558

On the

07 Mar 2024

By

Chris Daly BEng(Hons) MIFSM

1. Risk Summary
2. Risk Assessment
 - 01 - Persons at Risk
 - 02 - Sources of Ignition
 - 03 - Sources of Fuel
 - 04 - Construction
 - 05 - Means of Escape
 - 06 - Fire-fighting Equipment
 - 07 - Fire Detection and Warning
 - 08 - Emergency Lighting
 - 09 - Firefighters Provisions
 - 10 - Management
 - 11 - Signs and Signals
 - 12 - Effects on the Environment
3. Action Plan
4. Archive

FIRE RISK ASSESSMENT GUIDANCE NOTES

This Fire Risk Assessment has been compiled and formulated as required by the Regulatory Reform (Fire Safety) Order 2005, The Fire Safety (Scotland) Regulations 2006, The Fire & Rescue Services (NI) Order 2006 and The Fire Precautions (Workplace) Regulations (Northern Ireland Only). It has been constructed to be used as a tool for the safe management of a work place.

To use the Risk Assessment effectively follow the points below:-

1. Read the risk summary as a snap shot of the premises on the day of the Fire Risk Assessment. Recommendations from the Action Plan may have already been implemented by the time you read this.
2. The Risk Assessment is broken into the following twelve sections.
3. The Action Plan is the observations and recommendations of the Fire Assessor using their competence and experience to ensure the most pragmatic approach is applied to all significant findings.
 - a. Read the Action Plan in its entirety as some actions may have an impact on other recommendations.
 - b. Once the recommended action has been completed, the responsible person must sign and date the page relating to the non conformity this will then be automatically stored in the Archive Section which provides an audit trail.
4. It is essential that the Fire Log Book is maintained by the Responsible Person, to ensure that all tests, maintenance, practice drills and periods of instruction are recorded. If used as designed, this will then prove to be an invaluable Management tool.
5. If there are any material changes to the structure, layout, use of the building, type of business or changes in the number of staff then a new Fire Risk Assessment must be carried out. The Fire Risk Assessment should be reviewed by a competent person by the review date or at such earlier time as there is reason to suspect that it is no longer valid or there have been significant changes to the premises, the occupancy or its use. It is recommended to have a review carried out annually to ensure all fire safety measures and practices are being adhered to.

SECTION 1: MANAGEMENT OVERVIEW - RISK ASSESSMENT

Address
 1-70 Perryman House - Barking - 900011558
 1-70 Perryman House
 Barking
 IG11 7LA

Responsible Person
 London Borough of Barking & Dagenham

Article 5(3) Persons
 Delroy Sylvester

Telephone
 0208 277 727266

Email
 Delroy.Sylvester@lbbd.gov.uk



Building Id
 10035405
Assessment Id
 10112080

This Risk Assessment was carried out on 07 Mar 2024 and the assessor has stated that this building cannot be below Low risk.

Building Details:	
Assessor:	Chris Daly BEng(Hons) MIFSM
Checked By:	Chris Daly Date: 15/03/2024
Validated By:	Simon Churchill Date: 21/03/2024
Area:	5350
Number of floors:	12
Occupied floors:	12
Number of occupants:	140
Is customer LandLord?:	Yes
Type of alarm:	Category L5/M System

Live Fire Log Book	Next Due Date
Risk Assessment	07/03/2025
Fire Drill	NA
Fire extinguisher maintenance:	NA
Fire Safety Training	NA
Fire Marshal Training	NA
Fire Alarm Service	NA
Emergency Lighting Service	No Records

Description of Property

The premises is a purpose built 12 storey general needs block of flats.

The building is of traditional brick and blockwork construction and a flat roof. Internal block and plasterboard partitions. Concrete slab floors and stair. There is a concrete cladding finish to the exterior façade this is considered as low risk.

There is a single FD30s lobby protected concrete staircase from the ground floor serving flats on all floors. Two passenger lifts are installed within the ground floor lobby.

There are six apartments on each of the upper floors and four on the ground floor. Apartments are accessed direct from a communal corridor. There is a short protected corridor in each flat serving all rooms, lounge/kitchen, bedrooms and bathroom, and all doors are FD30 standard.

The apartments are provided with a self closing FD30s front door with fire-rated door handles, locks, thumb turns and with BS EN 1154 self closers and 3 x BS EN 1935 fire-rated hinges. Letterboxes are installed and appear to be fire proof. The ventilation from kitchens and bathrooms appear to vent externally to the building. There does not appear to be internal ventilation ductwork.

Each apartment has detection provided in the hall and kitchen area to BS5839-6 2019 Category LD2 standard.

Automatic smoke detection has been installed within the stairway and lobby to BS5839-1 L5 as part of a smoke control system to activate the automatic opening vent (AOV). The AOV's are located above the protected staircase in a form of an actuator operated opening window.

Electrical cupboards are installed on each floor. These are fitted with FD30s doors and kept locked shut.

There is a sprinklered refuse store on the ground floor at the front of the building and all kept secure.

Caretakers room/store is located within the ground floor lift lobby area and has an FD30s door which is kept locked shut.

Emergency lighting to BS5266 and fire exit signs are provided throughout the means of escape within the premises.

Dry riser inlet located adjacent to the front entrance door to the block. Outlets provided within the lobby on each floor.

Travel distances are within acceptable limits.

Secure entrance door entry system to the main stairwell at ground floor level. Fire fighters override button provided adjacent to the front door. Low risk of arson with adequate security measures.

A Type 3 (non-destructive) fire risk assessment was conducted out on the common parts and flats 70, 66, 65, 62, 58, 54, 52, 44, 42, 35, 30 and 21 only. No response from other residents.





This Risk Assessment was carried out on 07 Mar 2024 and this property was considered a Low risk property.

4	9	0
Actions required next service visit	Actions required within 30 days	Immediate actions required

To view actions outstanding [click here](#)

History of Incidents

None reported.

Risk Assessors Summary

The premises is occupied 24/7 as it is a residential property of 70 general needs flats. Building due for demolition, 73% of flats now vacant and have steel sheets on front doors for security purposes. Built circa 1960's.

Persons at risk; the building is occupied by residents that will be familiar with the premises. Contractors and visitors who may be unfamiliar with the layout. It was not known whether vulnerable residents are within the building.

Sources of ignition; the common areas are generally free from electrical installations. Electrical intakes. Fixed wiring, lightning. The distribution boards are located within a fire resisting cupboard located in on each floor. Non smoking premises. Low risk of arson with adequate security measures

Sources of fuel; the common areas of the building are generally kept free of combustible materials. Mains gas supply to flats. Additional refuse bins kept away from the building and kept secure.

Sources of oxygen; there are no additional sources of oxygen present.

The evacuation procedure for the premises is stay put. In the event of a fire residents are expected to remain in their flat where it is safe to do so. Occupants in the common areas will evacuate to a place of ultimate safety.

Premises information box installed within the ground floor stairwell. This is considered satisfactory for the size of the building.

The fire risk assessment has been conducted using a suite of documents, where appropriate, including HM Government Fire Safety in Purpose Built Block of Flats guide 2021, British Standards, Approved Document B of the Building Regulations, British Standards Institute PAS 9980 2022.

As this building contains two or more domestic premises and contains common parts through which residents would need to evacuate in the case of an emergency, the Fire Safety (England) Regulations 2022 apply. Regulation 9 Information to residents and Regulation 10 Fire doors apply to this premises.

As the building is 18m or more, or 7 storeys or more;
 Regulation 4 Secure Information box;
 Regulation 5 Design and materials of external walls;
 Regulation 6 Floor Plans and building plan;
 Regulation 7 Lifts and essential fire-fighting equipment;
 Regulation 8 Wayfinding signage;
 Regulation 9 Information to residents and;
 Regulation 10 Fire Doors,
 apply to this premises.

Speaking to residents it appears that the The client does not comply fully with the Fire Safety (England) Regulations 2022,

Unaccompanied visit.

SECTION 2: RISK ASSESSMENT

01 - Persons at Risk

It is important to consider all relevant persons that use the premises. This will include persons that use the building on a day to day basis such as staff or residents but also any persons that visit the premises on temporary basis such as visitor or contractors. Particular care should be taken to identify any risks to vulnerable persons such as those with disabilities or young persons.

Sub Section	Question	Answer	Action Plan	Status
01 - Young Persons	Are young persons in the premises?	There are no young persons present at the time of this fire risk assessment.		N/A
02 - Persons with Special Needs	Are persons with special needs in the premises?	There are no persons with special needs present at the time of this fire risk assessment.		N/A
03 - Members of the Public	Are members of the public present in the premises?	Members of the public are present and the Responsible Person has suitable and sufficient policies and procedures in place.		Compliant
04 - Occupancy Numbers	Is the occupancy level for the premises acceptable?	The occupancy capacity, width of escape routes and exits appear to be sufficient.		Compliant
05 - Lone Working	Are there areas where relevant persons are isolated?	At the time of this fire risk assessment Company policy prohibits the practice of lone working.		N/A

02 - Sources of Ignition

The premises is assessed to identify all potential ignition sources that may be the cause of a fire. Examples of Ignition sources can be any heat generating equipment such as portable heaters, cooking equipment and power tools. Fixed installations and portable electrical equipment can also be an ignition source if they are misused or not maintained. Naked flames and equipment that generates sparks must be strictly controlled.

Sub Section	Question	Answer	Action Plan	Status
01 - Heating - Gas and Electric - including Portables	Are all heating appliances correctly installed, adequately protected and maintained?	All appliances are correctly installed and adequately maintained.		Compliant
02 - Electrical Services	Are all electrical installations and appliances correctly installed and maintained?	There was no evidence of periodic inspections of the electrical installations having been carried out within the last 5 years.	A	Non-Compliant
02 - Electrical Services	Are all electrical installations and appliances correctly installed and maintained?	There was no evidence of periodic inspections of the lift installations.	2.0.C	Non-Compliant
03 - Lightning Protection	Is lightning protection provided for the building?	A lightning protection system has been installed, there is no evidence of periodic inspection and maintenance being completed.	B	Non-Compliant
04 - Miscellaneous	Are potential sources of ignition adequately controlled?	Potential sources of ignition present are adequately controlled.		Compliant

03 - Sources of Fuel

In order for a fire to develop the presence of fuel is required. By managing the quantity, type and location of combustible materials the risk of a fire developing can be greatly reduced. The storage of combustible materials within the escape routes or places of high fire risk such as boiler rooms or electrical cupboards must be prevented.

Sub Section	Question	Answer	Action Plan	Status
01 - Housekeeping	Are house keeping arrangements satisfactory?	Housekeeping arrangements appear to be satisfactory.		Compliant

04 - Construction

The fire protection of the building is required to ensure that fire is unable to spread and also to prevent premature collapse in the event of fire. It means that the occupants can safely exit the premises without undue risk, whilst it is not perceived that any building should be sacrificed it is always possible to avoid the loss of the premises.

Sub Section	Question	Answer	Action Plan	Status
01 - Structural Elements	Are the fire resisting and separating walls and floors in good condition?	The fire resisting walls and floors appear to be of an acceptable standard.		Compliant
02 - Lift Shafts	Are the lifts contained within protected shafts?	The lifts are contained within a protected shaft.		Compliant
03 - Protected Shafts	Are the escalators, chutes, ducts and pipes contained within protected shafts?	The services are contained within protected shafts.		Compliant
04 - Concealed Spaces - Cavities	Are the concealed spaces or cavities protected with suitable cavity barriers?	The cavity barriers appear to be acceptable.		Compliant
05 - Protected Stairways	Are the stairways within the building required for means of escape adequately enclosed with fire resisting construction?	The stairways are enclosed throughout their height to an acceptable standard.		Compliant
06 - Higher Risk Areas	Are areas of higher risk and places of special fire hazard sufficiently separated from the remainder of the building by fire resisting	The high risk areas and places of special fire hazard are adequately separated with		Compliant

construction?

fire resisting construction.

07 - Surface Spread of Flame	Are the materials used to line walls and ceilings of the correct surface spread of flame classification in accordance with the Approved Document B of the Building Regulations?	The materials lining the walls and ceilings are deemed to be of an acceptable standard.	Compliant
-------------------------------------	---	---	------------------

05 - Means of Escape

To ensure a safe escape the escape routes must be protected from smoke, heat and flames. The distance that occupants have to travel must also be regulated to ensure that the distance people have to travel to safety is within the prescribed guidelines.

Sub Section	Question	Answer	Action Plan	Status
01 - Means of Escape for the Disabled	Are there adequate arrangements for the evacuation of disabled people?	The evacuation arrangements for disabled people are considered adequate.		Compliant
02 - Premises that are multi-occupied	Are the escape routes for all the building occupants acceptable?	The premises are multi-occupancy and the means of escape from each occupancy is considered satisfactory.		Compliant
03 - Escape routes and travel distances from within a storey	Are the escape routes sufficient in number and travel distance from any point within the floor area to the nearest storey exit, having due regard to the layout of walls, partitions and fittings within current guidance?	The travel distance to the nearest storey exit is within current guidance.		Compliant
04 - Occupancy Numbers	Is the occupancy level for the premises acceptable?	The occupancy capacity and width of escape routes and exits appear to be sufficient.		Compliant
05 - Protected Corridors	Are the protected corridors suitable and sufficient to allow the occupants to reach a storey exit safely?	All protected corridors are adequate to allow the occupants to reach a storey exit safely.		Compliant
06 - Escape from Inner Rooms	Is the escape from inner rooms acceptable?	No risk from inner room situations present.		N/A
07 - Accommodation Lifts and Stairways	Are the accommodation lifts and or stairways positioned so that they do not impact on the escape routes from upper floors?	The position of accommodation lifts and or stairways is such that they do not prejudice the escape from upper floors.		Compliant
08 - Protected Stairways	Do the protected stairways offer sufficient and suitable protection to ensure the safe escape of all occupants?	Sufficient and protected stairways have been provided to ensure safe escape of all the occupants.		Compliant
09 - External Stairways	Is the external stairways provision sufficient and does it afford suitable protection to the occupants to ensure their safe escape?	No external stairways were present.		N/A
10 - Escape Route across a flat roof	Is the escape route across a flat roof acceptable?	Flat roofs do not form part of the escape route.		N/A
11 - Fire-resisting doors	Do the fire resisting door sets meet the appropriate standard?	The fire door requires a self-closing device.	K	Non_Compliant
11 - Fire-resisting doors	Do the fire resisting door sets meet the appropriate standard?	Ineffective self closing devices.	5.0.J	Non_Compliant
12 - Fire-resisting partitions	Are the fire resisting partitions present installed and maintained to the appropriate standards?	The fire resisting partitions within the building are constructed and maintained to an appropriate standard.		Compliant
13 - General Doors	Are the doors required to form part of the escape route in an emergency?	All the doors required to form part of the escape route are in good working order and are capable of being used effectively.		Compliant
14 - Housekeeping	Are house keeping arrangements satisfactory?	Combustible materials are located/stored in the escape routes.	A	Non_Compliant
14 - Housekeeping	Are house keeping arrangements satisfactory?	The escape route is obstructed.	5.0.D	Non_Compliant

06 - Fire-fighting Equipment

Fixed and portable firefighting equipment can be used to good effect and minimize damage to the premises. If a fire has been detected in its early stages fighting the fire in these early stages will contain its growth and reduce hazards to the occupants such as smoke and heat as well as minimising potential financial loss to the business and the impact on jobs.

Sub Section	Question	Answer	Action Plan	Status
01 - Portable Equipment	Are there sufficient quantities of portable fire-fighting equipment provided, correctly sited and adequately maintained?	Due to the type of premise the provision of portable fire-fighting equipment is not required.		N/A
02 - Fixed Fire-Fighting Installations	Are the fixed fire-fighting installations correctly installed, adequately maintained and appropriate for the risk?	The system is not tested in accordance with manufacturers' instructions and design criteria.	E	Non_Compliant

07 - Fire Detection and Warning

It is essential for the safe evacuation of building occupants that they have been made aware of a fire incident as soon as possible. This will allow the Fire

Service to be contacted in the early stages of the fire and most importantly all the occupants should have left the building to a place of safety before the fire has had the chance to take a hold. It is vital that any early warning and detection system be installed and maintained to British Standards.

Sub Section	Question	Answer	Action Plan	Status
01 - Fire Detection and Warning System Provision	Is there an adequate method for raising the alarm and detecting a fire present in the premises?	There is an appropriate method of raising the alarm and detection in the event of a fire.		Compliant
02 - Fire Alarm Maintenance	Is the fire alarm system routinely tested, inspected and maintained in accordance with current guidance?	No evidence available for the maintenance, testing and servicing of the automatic opening vent system (AOV).	NR-51-205-1	Non_Compliant

08 - Emergency Lighting

If the conventional lighting system fails in a building, an emergency lighting system may be required. The emergency lighting system should indicate the safe routes to and through the escape exits from the premises including any changes of direction or level en-route. It can also be used to illuminate fire alarm call points, refuges and firefighting appliances.

Sub Section	Question	Answer	Action Plan	Status
01 - The Emergency Lighting System	Is there an adequate method for illuminating the escape route and safety equipment in the premises?	It appears that the installed emergency lighting system will provide sufficient illumination (visual observation only, a physical test was not completed).		Compliant
02 - Maintenance of Emergency Lighting Systems	Is the emergency lighting system routinely tested, inspected and maintained in accordance with current guidance?	Not inspected and maintained in accordance with BS 5266-8.	A	Non_Compliant

09 - Firefighters Provisions

As required under the Regulatory Reform (Fire Safety) Order 2005, The Fire Safety (Scotland) Regulations 2006, The Fire & Rescue Services (NI) Order 2006 and The Fire Precautions (Workplace) Regulations (Northern Ireland Only) consideration must be made to the effects of a fire in any given building to the Fire Service. Safety of the fire crews and their operational needs such as access, water supplies and building information must be reviewed and be made available for the Fire Service for consideration.

Sub Section	Question	Answer	Action Plan	Status
01 - Access for Fire Fighting	Have reasonable facilities and access for firefighters and fire appliances been provided to aid the protection of life?	Facilities and access for firefighters and fire appliances are available and adequate.		Compliant
02 - Firefighter Safety	Have all reasonable measures and arrangements been made to safeguard firefighting personnel in a fire situation?	All reasonable measures and arrangements for the safety of firefighting personnel in a fire situation are in place.		Compliant
03 - Water Supplies	Are water supplies adequately provided to assist firefighting personnel in their firefighting tasks?	There is adequate hydrant provision of adequate diameter in close proximity to the premises.		Compliant
04 - Rising Mains	Are rising mains adequately provided to assist firefighting personnel in their firefighting tasks?	Dry riser are present but are not subject to periodic testing, inspection and maintenance.	D	Non_Compliant

10 - Management

Providing all of the elements of the fire safety plan (of which the fire risk assessment form just part) are adhered to, then the safe evacuation of all the occupants is then likely to be successful. If however the management of the fire safety plan is not adhered to the fire safety provisions may be seriously compromised.

Sub Section	Question	Answer	Action Plan	Status
01 - Management	Are management and employees fully aware of the fire safety features provided and their purpose?	Unable to confirm whether client is fully compliant with the Fire Safety (England) Regulations 2022 apply. In particular, Regulation 9 Information to residents and Regulation 10 Fire doors apply to this premises.	NR-54-212-2	Non_Compliant
02 - Staff Training	Have employees received appropriate fire safety awareness training?	This premises does not require employees to be trained.		N/A
03 - Housekeeping	Are house keeping arrangements satisfactory?	The housekeeping arrangements appear to be of an acceptable standard.		Compliant
04 - Arson	Are adequate measures in place to control risk of fire due to arson?	Adequate arson control measures are in place.		Compliant
05 - Smoking Policy	Is a suitable 'no smoking' policy in place?	Evidence of unauthorised smoking was found.	B	Non_Compliant
06 - Legislation	Has the premises been subject to an inspection by the Enforcing Authority?	The premises have not been subject to an inspection by the Enforcing Authority.		N/A

11 - Signs and Signals

Research has shown that members of the public may become confused and disorientated in the event of a fire. To save confusion which can jeopardise building occupants escape all safety signs should be installed and conform to Signs and Safety Signals Regulations.

Sub Section	Question	Answer	Action Plan	Status
01 - Provision of Fire safety Signs and Notices	Are there adequate and suitable fire safety signs and notices displayed in the appropriate places throughout the premises?	Fire safety signs and notices are provided to the appropriate standards.		Compliant

12 - Effects on the Environment

A further requirement under the Regulatory Reform (Fire Safety) Order 2005, The Fire Safety (Scotland) Regulations 2006, The Fire & Rescue Services (NI) Order 2006 and The Fire Precautions (Workplace) Regulations (Northern Ireland Only) is that consideration must be made to the effects of a fire in any given building to the environment. The spread of fire to adjacent properties, the risks posed by the smoke from the materials contained within the building if affected by fire and if the water used for firefighting needs to be contained to protect the water course.

Sub Section	Question	Answer	Action Plan	Status
01 - Adjacent Properties	Has the Responsible Person considered the effects to adjacent buildings that might be caused by a fire on the site?	The Responsible Person has made adequate arrangements to mitigate any damage to the adjacent properties from a fire on the site.		Compliant
02 - Immediate Surroundings	Has the building's Responsible Person considered the effects to the environment that might be caused by a fire on the site?	The Responsible Person has made arrangements to mitigate any damage to the environment from a fire on the site.		Compliant

SECTION 3: ACTION PLAN

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093860	2.0.C	Are all electrical installations and appliances correctly installed and maintained?	There was no evidence of periodic inspections of the lift installations.	If evidence of an inspection is unavailable, a competent person is to inspect the lift installations and records maintained.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093863	5.0.J	Do the fire resisting door sets meet the appropriate standard?	Ineffective self closing devices.	Repair or replace the self-closing device to ensure fire door/s close fully into their frame against the door stops.	Lobby door on 5th floor	Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

IMG_5953(1).jpg



Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093859	A	Are all electrical installations and appliances correctly installed and maintained?	There was no evidence of periodic inspections of the electrical installations having been carried out within the last 5 years.	If evidence of an inspection is unavailable, a competent electrician is to inspect all electrical installations throughout the premises in accordance with IEE Regulations (BS 7671) and records maintained.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093868	A	Is the emergency lighting system routinely tested, inspected and maintained in accordance with current guidance?	Not inspected and maintained in accordance with BS 5266-8.	The emergency lighting system must be inspected and maintained by a competent certified organisation in accordance with BS 5266-8.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes: _____
 No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093861	B	Is lightning protection provided for the building?	A lightning protection system has been installed, there is no evidence of periodic inspection and maintenance being completed.	The lightning protection system is to be inspected and maintained by a competent person in accordance with BS 6651. Records are to be maintained.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes: _____
 No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093869	D	Are rising mains adequately provided to assist firefighting personnel in their firefighting tasks?	Dry riser are present but are not subject to periodic testing, inspection and maintenance.	The dry riser should be tested, inspected and maintained in accordance with BS 9990.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093866	F	Are the fixed fire-fighting installations correctly installed, adequately maintained and appropriate for the risk?	The system is not tested in accordance with manufacturers' instructions and design criteria.	Ensure the system is tested and maintained in accordance with manufacturers' instructions and/or current British Standard.	Sprinklers	Statutory requirement of the Client	23/04/2024

Completed By..... Date.....

Action Status Notes: _____
 No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093862	K	Do the fire resisting door sets meet the appropriate standard?	The fire door requires a self-closing device.	The fire doors indicated must be fitted with a suitable positive action self-closing device (BS EN 1154).	Flats 70, 66,. 57 and 42.	Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

IMG_5949(1).jpg



Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Medium Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093867	NR-51-205-1	Is the fire alarm system routinely tested, inspected and maintained in accordance with current guidance?	No evidence available for the maintenance, testing and servicing of the automatic opening vent system (AOV).	The AOV system must be tested, then inspected and maintained by a competent certificated organisation in accordance with BS12101. Compliance certificate to be provided.		Statutory requirement for the Client	23/04/2024

Completed By..... Date.....

Action Status Notes:
 No notes have been entered

Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Low Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093865	5.0.D	Are house keeping arrangements satisfactory?	The escape route is obstructed.	The items obstructing the escape route must be removed..	O/S Flats 36 and 30.	Statutory requirement for the Client	22/06/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

IMG_5951(1).jpg



IMG_5952(1).jpg



IMG_5954(1).jpg



Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Low Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093864	A	Are house keeping arrangements satisfactory?	Combustible materials are located/stored in the escape routes.	Items that are a source of fuel or are combustible and likely to increase the fire loading or spread of fire, should not be located on any corridor, stairway or circulation space that will be used as an escape route. Therefore, the combustible materials stored in the escape routes must be removed.	O/S Flat 69, 14 and 13.	Statutory requirement for the Client	22/06/2024

Completed By..... Date.....

Action Status Notes:
No notes have been entered

IMG_5950(1).jpg



IMG_5956(1).jpg



IMG_5955(1).jpg



Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Low Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093871	B	Is a suitable 'no smoking' policy in place?	Evidence of unauthorised smoking was found.	Management are to apprise all relevant persons on the company smoking policy.	11th floor stairwell	Statutory requirement for the Client	22/06/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

IMG_5947(1).jpg



Locations of Non-conformity (one floorplan per page)

SECTION 3. ACTION PLAN:Low Risk Actions

All non conformities should be reviewed in conjunction with the CAD or the photographic evidence where applicable.

Ref	Sub Section	Question	Non-conformity	Recommendation	Location	Who is responsible	By When
13093870	NR-54-212-2	Are management and employees fully aware of the fire safety features provided and their purpose?	Unable to confirm whether client is fully compliant with the Fire Safety (England) Regulations 2022 apply. In particular, Regulation 9 Information to residents and Regulation 10 Fire doors apply to this premises.	As this building contains two or more domestic premises and contains common parts through which residents would need to evacuate in the case of an emergency, the Fire Safety (England) Regulations 2022 apply. Regulation 9 Information to residents and Regulation 10 Fire doors apply to this premises. As the building is 18m or more, or 7 storeys or more; Regulation 4 Secure Information box; Regulation 5 Design and materials of external walls; Regulation 6 Floor Plans and building plan; Regulation 7 Lifts and essential fire-fighting equipment; Regulation 8 Wayfinding signage; Regulation 9 Information to residents and; Regulation 10 Fire Doors, apply to this premises. Client to ensure full compliance with all regulations, in particular, residents are to be updated with Regulation 9 and 10.		Statutory requirement of the Client	22/06/2024

Completed By..... Date.....

Action Status Notes:

No notes have been entered

Locations of Non-conformity (one floorplan per page)

